


## Lost Cleaning Pig in Thompson Pass Pressure Relief System At Valdez Marine Terminal, January 2000



Valdez, January 2000: 48-inch diameter scraping cups of errant cleaning pig squeeze through 18" valve block in Thompson Pass backpressure system.

– Joint Pipeline Office, *A Look at Alyeska Pipeline Service Company's Operation of the Trans-Alaska Pipeline System 1999/2000*, p. 24 (4.3.2 Backpressure System Damage/Pig#4 Incident)