


Site of “Spool Piece” at TAPS Pump Station 8, January 2011



The section of pipe at Pump Station 8 in which the northern PIG was trapped [on the right] and the bypass line (on the left) through which oil is being diverted around it (Photo Date: 1/12/2011) .

– Photo Credit: Alaska Department of Environmental Conservation
(Image 7 of 19 from Pump Station 1 Booster Pump Piping Incident:
Photo Gallery)

[Note: Pump Station 8, near Salcha, has been closed since June 1996.]

Accessed 12/21/19 at
http://dec.alaska.gov/spar/perp/response/sum_fy11/110108301/gallery/110108301_gal_01/index.htm